

J 1000, 1000 RTD Ni1000/6180 ppm 1000, 1000 MS 1000000

1000: M1018



1000: -50 100°C ($\pm 0.2^\circ\text{C}$), 100 250°C ($\pm 0.2\%$). 10000. 20000

1000