

Pt1000TG7/0, 200, 20, 2000

SN: SN165



PT1000 sensor -30 to +200°C.

CINCH connector

-30 to +200°C, $\pm(0,15+0,002 |t|)$.

18mm, 6.5mm, 20

M4 connector. IP65.

Temperature sensor

2000