

031-60, Ni100



SN130

Ni1000/6180
-10 to 60°C.
 $\pm(0.3+0.005*|t|)$.

CINCH